

ASBESTOS SAMPLING REPORT

Scott Henderson on behalf of Taranaki Builders Ltd trading as Betta Inspect It
Admin Office: PO Box 11157, Hastings, 4158
Free Phone: 0800 422 388
info@bettainspectit.co.nz

Friday, 26th May 2017
McDonalds Real Estate.
RE: ASBESTOS SAMPLING REPORT

Test requested by:	Realestate Agent
Sample date:	26/05/2017
Reference number:	38592
Type of property:	Residential dwelling
Property address:	77 Cressida Ave, Stratford, 4332
Number of samples taken:	1
Date samples sent to the lab:	26/5/2017

LABORATORY RESULTS

IS ASBESTOS PRESENT? NO - (No asbestos detected on the samples taken)

The above results are from an inspection of the property undertaken by Scott Henderson on behalf of Taranaki Builders Ltd trading as Betta Inspect It which are analysed by RJ Hill Laboratories, an independent IANZ accredited laboratory.

Please note that samples were only taken at the locations referred to in the report.

What happens if asbestos is present?

IF asbestos is present please refer to the following websites for further information:

<http://www.business.govt.nz/worksafe/information-guidance/all-guidance-items/asbestos-factsheets>
<http://www.business.govt.nz/worksafe/information-guidance/guidance-by-hazard-type/asbestos/about-asbestos>
<http://www.health.govt.nz/your-health/healthy-living/environmental-health/hazardous-substances/asbestos>

Thank you for choosing Scott Henderson on behalf of Taranaki Builders Ltd trading as Betta Inspect It to undertake your asbestos sampling. We appreciate your business, and look forward to being of service to you should you have any future testing requirements.

Kind Regards

Scott Henderson on behalf of Taranaki Builders Ltd trading as Betta Inspect It




SAMPLE LOCATION PHOTOS

Sample Location


Entrance.



Lounge.



Dinning room.



Packaged Samples

